

## **MIRASYS 9.7.1 RELEASE NOTES**

#### Release date 19 March 2024

### Important Notes

- 1. Mirasys VMS V9 is only available as a 64-bit version.
- 2. A V9 Master Server (Management Server) can handle 64-bit V8 and V9 servers.
- 3. The Complete Installer will automatically install the SQL Server Express 2019 or upgrade an earlier SQL installation to 2019 on 64-bit systems.
- 4. A 32-bit (x86) SQL Server Express 2008 version will not be upgraded to the 64-bit (x64) SQL Server Express 2014. Update SQL manually before updating from an old 32-bit V7 to the latest 64-bit version!

### Supported OS

- Windows 10 IOT/Pro
- Windows 11 (V9.4 or later)
- Windows Server 2016
- Windows Server 2019
- Windows Server 2022 (since V9.5.0)

#### Free 12-month SMA

Free 12-month SMA offer for new licenses and licenses acquired until December 31st, 2024.







#### VMS V9.7.1 Enhancement

Driver version is displayed with the Driver in System Manager Camera Settings under Camera Driver information.

The ONVIF Driver is updated. The latest version will skip PTZ presets loading when the device has been configured in the Driver XML file.

### VMS V9.7.1 Fixes

#### Spotter

Fixed: Export to Storage Locker works as intended.

Fixed: Spotter settings saving works as intended for imported AD users.

Fixed: Error message displayed when tab content is not saved due to SM Server being down.

Fixed: The forklift and other vehicle attribute visualization in VCA Core have been added in Spotter.

Fixed: Smart Search plugin search renders correct search results for 1000 results and above.

Fixed: Smart List Management plugin shows buttons when numerous face images are added for the identity.

Fixed: Spotter is showing VCA metadata correctly.

Fixed: Spotter works as intended when previewing Storyboard.

Fixed: Users are not able to access a password-protected shared bookmark.

Fixed: Spotter Smart Search plugin displays correct percentage values in the Identity column.

Fixed: Password is saved as encrypted text in the Spotter settings file.

Fixed: Spotter converts metadata correctly.









### Spotter Web

Fixed: Removing a removed camera from the view works as intended.

Fixed: Alarm events duration and the time since the alarm start is clear and consistent in the alarm list in Spotter Web.

Fixed: In Spotter Web Export, 64-character file names fit within the export progress dialog.

Fixed: Spotter Web shows devices on the export dialog in Firefox.

Fixed: Spotter Web profile loading works as intended.

Fixed: Live stream opening works as expected when the same stream is opened from several clients simultaneously.

#### System Manager

Fixed: When the "Driver" field is empty in the CSV file, all selected drivers are used for the capability query. If both native and ONVIF drivers can be used, then the ONVIF is used by default.

Fixed: HTTP error handling works as intended in System Manager.

Fixed: Spotter role settings playback limit time is not reset to 5 minutes by default, instead of keeping the playback limit time previously defined by the user.

Fixed: Saved alarms work as intended in the UI alarm list in System Manager.

Fixed: The System Manager works as intended after digital I/O configuration changes.

Fixed: When multiple devices of the same kind are selected from the profile tree in profile settings, the shortcut number is not changed.

Fixed: System Manager displays an error to the user that the download has failed when VAU cannot download Spotter.

Fixed: The profile tree in profile map settings will work as intended when clicking the device on the tree.









#### VMS Server

Fixed: Material copy works as intended.

Fixed: Failover works as intended during upgrades to V9.7.

Fixed: When recording for 72h, there is only data for 72h.

Fixed: VMS server stops correctly (without "pure virtual call" error in log) with enabled RTSP streams for IP cameras.

Fixed: VCA configuration from the backup file can be restored to a recorder whose address differs from the recorder in the backup.

Fixed: When a network MOXA IO device is added to the VMS Server and the network connection is broken, the user will only get one error message in the recorder log.

#### FR, LPR and LM

Fixed: List Manager Service installation works as intended.

Fixed: To prevent extra memory load and slowing down of process startup, files for the LPR region, as well as devices, must be selected upon installation instead of being automatically included.

#### System

Fixed: When restoring the V9.6 backup to V9.7, VCA settings work as intended, and configurations and created engine files are intact.

Fixed: Failover VMS version number is displayed correctly.

Fixed: Pre-recording functionality works as intended.









#### **Drivers**

Fixed: Hikvision EasyLPR is working as intended with latest Hikvision Driver.

Fixed: Privacy mask/zone now updating on the camera side with the ONVIF Driver.

Fixed: Audio in the Bosch Driver works as intended.

Fixed: The Hikvision Driver supports the Hikvision DS-2CD6365G1-IVS camera.









#### Legal Notice for Mirasys Video Management Software Release Notes

Copyright © 2024 Mirasys Oy All rights reserved.

**License Agreement:** This software and its documentation are provided to the licensed client under the Mirasys License Agreement terms and conditions. By installing, copying, downloading, accessing, or otherwise using the Mirasys Video Management Software, you agree to be bound by these terms. If you do not agree to the terms of this agreement, do not install or use this software.

**Copyright Notice:** This software and accompanying documentation are copyrighted works of Mirasys Oy Unauthorized reproduction, distribution, or use of this software and/or documentation may result in severe civil and criminal penalties and will be prosecuted to the maximum extent possible under law.

**Disclaimer of Warranty**: Mirasys Video Management Software is provided "as is" without warranty of any kind, either express or implied, including but not limited to the implied warranties of merchantability, fitness for a particular purpose, or non-infringement. The entire risk arising out of use or performance of the software remains with you.

**Limitation of Liability**: In no event shall Mirasys Oy or its suppliers be liable for any damages whatsoever (including, without limitation, damages for loss of business profits, business interruption, loss of business information, or any other pecuniary loss) arising out of the use of or inability to use this Mirasys product, even if Mirasys Oy has been advised of the possibility of such damages.

**Third-Party Notices**: This software may contain third-party software components that are subject to open-source and third-party license terms. Your use of these components is subject to the terms and conditions of the respective license agreements, which can be found in the documentation or provided with the software package.

**Use Restrictions**: This software is licensed to the client and is not sold. The software may be used only by the licensed client and its authorized users within the organization. Sharing this software with individuals outside of the organization, or allowing its use by unauthorized users, is strictly prohibited and may result in termination of the license agreement.

**Export Control**: You agree to comply with all applicable international and national laws that apply to the software, including the export control laws of your jurisdiction as well as the United States.

**Changes to Terms**: Mirasys Oy reserves the right to make changes to this legal notice and the terms of the license agreement at any time without prior notice. Your continued use of the software will be considered acceptance of such changes.

**Governing Law**: This notice shall be governed by and construed in accordance with the laws of Finland without giving effect to any principles of conflicts of law.

**Contact Information**: For any questions regarding this legal notice or the licensing of the software, please contact Mirasys Oy at: https://support.mirasys.com



